PAS® X-plore® US
Supplied airline respirator

Notes on Approval

Dräger

Dräger Safety AG & Co. KGaA
D-23560 Lübeck, Germany
Phone: 011 49 451 882-(
or USA 1-800-437-2437

National Institute for Occupational Safety and Health NIOSH®

THESE RESPIRATORS ARE APPROVED ONLY IN THE FOLLOWING CONFIGURATIONS

Respirator Components

TC-	PROTECTION[1]	BASIC UNIT	ALTERNATE FACEPIECES										LDV ALTERNATE HOSES	
		3723029 PAS X-plore NIOSH with whistle	R61844 FPS 7000 P-EPDM-S1-APECas-H (US)	R61845 FPS 7000 P-EPDM-M2-APECas-H (US)	R61846 FPS 7000 P-EPDM-L3-APECas-H (US)	3707928 FPS 7000 P-EPDM-S1-PC-EPDM (NIOSH)	R57820 FPS 7000 P-EPDM-M2-PCas-EPDM (NIOSH)	R56200 FPS 7000 P-EPDM-M2-PC-EPDM (NIOSH)	R56300 FPS 7000 P-EPDM-L2-PC-EPDM (NIOSH)	R52972 Panorama Nova EPDM-PC-P	R53070 Panorama Nova Silikon P PC	3338712 Plus LDV (Push-in) / NIOSH LDV complete assembly compilation NIOSH LDV Assy 470 lg Hose c/w Hose Plug	3351378 LDV Extension hose
19C-0595	SA/PD	X	X	X	X	X	X	X	X			X	X
19C-0596	SA/PD	X								X	X	X	X

TC-	PROTECTION[1]	ALTERNATE CARRYING HARNESS							ALTERNATE HAIRNET	
		3363425 Backplate comfortable padding	3363461 Welding belt (leather L 1220 mm)	3363462 Welding belt size L (leather L 1420 mm)	3363680 Waist belt (PES-FR) with buckle (1280 mm)	3363681 Waist belt decon (PES-bs.) with buckle (L 1280 mm)	3363682 Waist belt (PES-FR) with buckle (1780 mm)	3363683 Waist belt decon (PES-bs.) with buckle (L 1780 mm)	R56197 Hairnet FPS 7000	R61787 Hairnet FPS 7000 (US)
19C-0595	SA/PD	X	X	X	X	X	X	X	X	X
19C-0596	SA/PD	X	X	X	X	X	X	X		

TC-	PROTECTION[1]	ALTERNATE AIR SUPPLY HOSES / COUPLINGS																											
		4059357 5' length Heavy Duty Hose	4059061 25' length Heavy Duty Hose	4059062 50' length Heavy Duty Hose	4054854 75' length Heavy Duty Hose	4059063 100' length Heavy Duty Hose	4057757 5' length Light Duty Hose	4057761 25' length Light Duty Hose	4057762 50' length Light Duty Hose	4057754 75' length Light Duty Hose	4057763 100' length Light Duty Hose	4059247 Socket and Union – Hansen Brass	4059248 Plug and Nut – Hansen Brass	4050835 Socket and Union – Hansen SS	4050836 Plug and Nut – Hansen SS	4059251 Socket and Union – Snaptite	4059252 Plug and Nut – Snaptite	4059249 Socket and Union – Schrader	4059250 Plug and Nut – Schrader	4051993 Socket and Union – Foster SS	4051992 Plug and Nut – Foster SS	4059253 Socket and Union – CEJN	4059254 Plug and Nut – CEJN	4050437 Hansen SS adapter	4059051 Hansen adapter	4050618 Foster adapter	4059054 Schrader adapter	4059056 Snaptite adapter	4059080 CEJN adapter
19C-0595	SA/PD	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
19C-0596	SA/PD	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X

TC-	PROTECTION[1]	ACCESSORIES																				Cautions and Limitations[2]
		R56230 Spectacle Kit FPS 7000	R51548 Spectacle Kit PN	4053437 Welding Shield PN	R58707 Welding visor FPS 7000	R62754 FPS-COM 5000 P VA	R62755 FPS-COM 5000 P UNIVERSAL	R62756 FPS-COM 5000 P WARIS	R62757 FPS-COM 5000 P JEDI	R62758 FPS-COM 5000 P GCAI	R62759 FPS-COM 5000 P KENWOOD	R62845 FPS-COM 5000 P BT MOTOROLA APX	R62728 FPS-COM 5000 P BT MOTOROLA DP	R61323 FPS-COM 7000 P VA	R61324 FPS-COM 7000 P UNIVERSAL	R61325 FPS-COM 7000 P WARIS	R61326 FPS-COM 7000 P JEDI	R61327 FPS-COM 7000 P GCAI	R61328 FPS-COM 7000 P BT MOTOROLA US	3357527 LDV Holder (P) ACCESSORY	R56375 Transponder disk	
19C-0595	SA/PD	X			X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	BCDEJMNOS
19C-0596	SA/PD		X	X																X	X	BCDEJMNOS

1. Protections
PD - Pressure Demand
SA - Supplied Air

2. Cautions and Limitations
B - Not for use in atmospheres immediately dangerous to life or health.
C - Do not exceed maximum use concentrations established by regulatory standards.
D - Airline respirators can be used only when the respirators are supplied with respirable air meeting the requirements of CGA G-7.1 Grade D or higher qua
E - Use only the pressure ranges and hose lengths specified in the User's Instructions.
J - Failure to properly use and maintain this product could result in injury or death.
M - All approved respirators shall be selected, fitted, used, and maintained in accordance with MSHA, OSHA, and other applicable regulations
N - Never substitute, modify, add, or omit parts. Use only exact replacement parts in the configuration as specified by the manufacturer.
O - Refer to User Instructions, and/or maintenance manuals for information on use and maintenance of these respirators.
S - Special or critical User Instructions and/or specific use limitations apply. Refer to User Instructions before donning.

© Dräger Safety AG & Co. KGaA

Dräger Safety AG & Co. KGaA
Revalstraße 1
23560 Lübeck, Germany
www.draeger.com
Tel +49 451 882 0
Fax +49 451 882 20 80