

Supplement to the instructions for use

This supplement applies to the medical devices listed in the table, starting from SW 3.33.

Medical device	Part number	Edition
Fabius GS <i>premium</i>	9038923	7th edition and higher
Fabius Tiro	9038686	7th edition and higher
Fabius plus	9039054	4th edition and higher
Fabius plus XL	9052882	1st edition and higher
Fabius MRI	9039036	8th edition and higher

- Enclose this supplement with the instructions for use for the medical device.

WARNING

To properly use this medical device, read and comply with the instructions for use and this supplement.


This supplement updates the information in the following chapter of the instructions for use:

Fault – Cause – Remedy

Priority	Alarm Message	Probable Cause	Remedy
! (9)	PEEP HIGH	PEEP is higher than 8 cmH ₂ O (hPa) in ManSpont mode.	Check APL valve setting and/or fresh-gas flow.



Directive 93/42/EEC
Concerning Medical Devices

 Manufacturer

Dräger Medical GmbH

 Moislinger Allee 53 – 55
D-23542 Lübeck
Germany
 +49 451 8 82-0
FAX  +49 451 8 82-20 80
 <http://www.draeger.com>

9053557 – en

© Dräger Medical GmbH

Edition: 4 – 2015-01

(Edition: 1 – 2012-01)

Dräger reserves the right to make modifications
to the device without prior notice.



As of 2015-08:
Dräger Medical GmbH
changes to
Drägerwerk AG & Co. KGaA